ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

M08957 Client ID: Date Received: 05/31/12 06/01/12 Date Extracted: Date Analyzed: 06/04/12 Matrix: Water Units: ug/L (ppb)

Project: Lab ID: Data File: Instrument:

Client:

Alaskan Copper Works Metro Self Monitor M08957

205455-01 x10 205455-01 x10.031 ICPMS1

Operator: AP

Lower

Internal Standard: Germanium

% Recovery: 94

Limit: 60

Upper Limit: 125

Concentration

Analyte:

ug/L (ppb)

505 Chromium Nickel 668 Copper 1,000 Zinc 179

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Date Received: Not Applicable Date Extracted: 05/31/12 Date Analyzed: 06/04/12 Matrix: Water Units: ug/L (ppb)

Client: Project: Lab ID: Data File: Instrument:

Operator:

Alaskan Copper Works Metro Self Monitor M08957 I2-349 mb

I2-349 mb.023 ICPMS1 AP

Lower

Upper

Internal Standard: Germanium

% Recovery: 95

Limit: 60

Limit: 125

Concentration ug/L (ppb)

<1

<1

Chromium Nickel Copper

Zinc

Analyte:

ENVIRONMENTAL CHEMISTS

Date of Report: 06/06/12 Date Received: 05/31/12

Project: Metro Self Monitor M08957, F&BI 205455

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 205402-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Percent Recovery MSD	Acceptance Criteria	RPD (Limit 20)
Chromium	ug/L (ppb)	20	<1	97	99	71-130	2
Nickel	ug/L (ppb)	20	<1	97	99	71-120	2
Copper	ug/L (ppb)	20	6.36	98 b	100 b	52-134	2 b
Zinc	ug/L (ppb)	50	26.5	93 b	103 b	51-142	10 b

Laboratory Code: Laboratory Control Sample

			${f Percent}$	
	Reporting	Spike	Recovery	Acceptance
Analyte	Units	Level	LCS	Criteria
Chromium	ug/L (ppb)	20	102	80-119
Nickel	ug/L (ppb)	20	104	83-119
Copper	ug/L (ppb)	20	104	81-120
Zinc	ug/L (ppb)	50	101	82-120

ENVIRONMENTAL CHEMISTS

<u>Data Qualifiers & Definitions</u>

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

205	455	12	SA	MPLE CHA	IN OF C	eus	то	DY		ME	5	05		31-	12		
Send Report To Geralis Company ALASKAN Address 628 S.	Corper	<u>َ س</u> ِ		PROJECT NA Medeo S	AME/NO.	1111	ni 4c	n	-3	n)# 355	7	, R	Stan RUS ush c	URN dard H_ harge	AROUND TIME (2 Wooks)
City, State, ZIP Search Phone # 206-571-60				REMARKS		I STATE	W			ANA	LYS	ES R	EQU	0	Disp Retu Will	090 a	PLE DISPOSAL fter 30 days unples with instructions
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B		_	HFS	ORCH MEZN				M. 1. 400	Notes
M08957	01	5/51/12	12:30	HW								X		1000	25.33		
3	τ.					2										140	
												-					
		i			i		1	1	1	1	1	130	-		н		1.4

Friedman & Bruya, Inc. 3012 16th Avenue West

Seattle, WA 98119-2029

Ph. (206) 285-8282

Fax (206) 283-5044

FORMS\COC\COC.DO(

7
12
:37
:37Pm
TIME
•

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

June 6, 2012

Gerald Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on May 31, 2012 from the Metro Self Monitor M08957, F&BI 205455 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0606R.DOC

205	455	fa 16	SA	MPLE CHA	IN OF C	:US	TO:	DY	v v	ME	E 08		}(- (12.	AIZ
Send Report To Genals Company ACASKAN Address 628 S. City, State, ZIP Seary Phone # 26-571-608	GRAPEN HVIN LE CUN	1 Wo 1 S81	134	PROJECT NA Medeo S REMARKS	AME/NO.		n'4c	n		n	PO#	7	Rus	tandar USH_ sh charg SAM Dispose seturn s	NAROUND TIME 1 (2 Wooks) 4 (2 Wooks) 2 (2 Wooks) 4 (2 Wooks) 4 (2 Wooks) 2 (2 Wooks) 2 (2 Wooks) 4 (2
Those #	Tax# ==	1	7 3 0 7		I	ſ			30.84	ANĀ	LYSES F	EQU		-8356	with instructions
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS ORCU NEZN				Notes
M08957	01	5/81/12	12:30	40	/						X				
						4				100					

Friedman & Bruya, Inc. 3012 16th Avenue West

Seattle, WA 98119-2029

Ph. (206) 285-8282

Fax (206) 283-5044

FORMS\COC\COC.DOC

SIGNATURE	PRINT NAME	COMPANY	DATE TIME
Relinquined by:	Genera I	1 Acw	S/21/2 1:37Pm
Rectived by: Au G M. Relinguished by:	Nhan Phan	FaBT	5 31 2 1:37
Received by:		Samples recei	ved at 21 °C